

UNCLASSIFIED

AD NUMBER

AD376829

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution
unlimited

FROM:

Distribution: USGO: others to Director,
Defense Atomic Support Agency, Washington,
D. C. 20301.

AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr
1997

THIS PAGE IS UNCLASSIFIED

628

卷之三

DDC FILE COPY

A vertical ellipsis symbol consisting of three horizontal dashes arranged vertically.

Cin. c. / Rep no.
~~TECHNICAL LIBRARY~~
~~or 1590/65~~
~~of the~~
~~29 NOV 1965~~
DEFENSE ATOMIC
SUPPORT AGENCY

Facsimile Report


دیوان

四百九

תְּהִלָּה בְּהַתְּבָאָה

Reproduced by
**UNITED STATES
ATOMIC ENERGY COMMISSION**

Division of Technical Information



This material contains information affecting the national defense of the United States within the meaning of the espionage laws, Title 18, U.S.C., Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

一九

*Group 3 applies per Mr. Niles, DAS Security off. Alderby
16 Nov 66.*

REF ID:	WHITE STATION	<input type="checkbox"/>
REF ID:	SUFF SECTION	<input checked="" type="checkbox"/>
REF ID:	DOC	<input type="checkbox"/>
CARTON NUMBERED		
JEWELERY		
BY		
DISTRIBUTION/AVAILABILITY CODES		
DIST.	AVAIL. and/or SPECIAL	
3		

IN ADDITION TO SECURITY REQUIREMENTS WHICH
APPLY TO THIS DOCUMENT AND MUST BE MET,
EACH TRANSMITTAL OUTSIDE THE AGENCIES OF
THE U.S. GOVERNMENT MUST HAVE PRIOR APPROVAL
OF THE DIRECTOR, DEFENSE ATOMIC SUPPORT AGENCY,
WASHINGTON, D.C. 20301.

CONFIDENTIAL

XRD

77

(14) XRD-77

(9) BUREAU OF SHIPS GROUP
TECHNICAL INSPECTION REPORT

DISTRIBUTION LIMITED

CONTAINS WEAPON DATA

GROUP 3

Downgraded at 12 Year Intervals

Not Automatically Declassified

Operation Crossroads U.S.S. LST 545

TESTABLE [REDACTED]

Original from Board of Inspection and Survey

This document contains neither recommendations nor conclusions of the National Defense Science Commission or its personnel. It is the property of the Commission and is loaned to your agency; its contents are not to be distributed outside your agency without the written permission of the Commission.

Institution (changed to COMINT) _____
by Authority of Joint Chiefs of Staff (JCS) _____ Date MAY 16 1952
By _____

OPERATION CROSSROADS

DIRECTOR OF SHIP MATERIAL

JOINT TASK FORCE ONE

CONFIDENTIAL
Security Information
Atomic Energy Commission

REG. NO. 48

8928

(B)

(11) 1946

(12) 1948

(193600) M

CONFIDENTIAL

CONFIDENTIAL

BUREAU OF SHIPS GROUP


TECHNICAL INSPECTION REPORT

TABLE OF CONTENTS

PAGE NO.

	PAGE NO.
Ship Characteristics Sheet -	3
Midship Section -	4
Overall Summary of Damage -	5
Hull Technical Inspection Report (Section I) -	11
Machinery Technical Inspection Report (Section II) -	16
Electrical Technical Inspection Report (Section III) -	22
Photographic Section (Section IV) -	29
Commanding Officers Report (Appendix) -	32

GROUP 3
Downgraded at 12 year intervals
Not Automatically Declassified



CONFIDENTIAL

Classification: Confidential (Changed to Secret by [Signature] Date: 15 APRIL 1960)
By [Signature] Date: 15 MAY 1960

Declassification: The information contained herein is confidential and is to be handled in accordance with the National Defense Information Organization (NDIO) Declassification Guide. It is prohibited by law to publish or otherwise disclose this information without authorization.

APPROVED:

F.X. Forest,
Captain, U.S.N.

USS LST 545

Page 1 of 33 Pages

CONFIDENTIAL

Classification: Confidential (Changed to Secret by [Signature] Date: 15 APRIL 1960)
By [Signature] Date: 15 MAY 1960

USS LST 545

Page 2 of 33 Pages

CONFIDENTIAL

Classification: Confidential (Changed to Secret by [Signature] Date: 15 APRIL 1960)
By [Signature] Date: 15 MAY 1960

REF ID: A6567545
AMERICAN MEMORY SYSTEMS

CONFIDENTIAL

U.S.S. LST 546

SHIP CHARACTERISTICS

Building Yard: Missouri Valley B. and I. Co., Evansville,
Indiana.

Commissioned: 23 March 1944.

HULL

Length Overall: 328 feet 0 inches.
Length on Waterline: 316 feet 0 inches.
Beam (extreme): 60 feet 0 inches.
Drafts at time of test: Fwd. 7 feet 2 inches.
Aft. 12 feet 3 inches.
Limiting displacement: 4,080 tons.
Displacement at time of test: 3,504 tons.

MAIN PROPULSION PLANT

Main Engines: Two General Motors Diesels, type:
12 - 667 A. One per main shaft.
Reduction Gears: "Falk" - Single reduction. One
per engine.
Propellers: Two are installed in ship.
Main Shafts: Two are installed in ship.
Ships Service Generators: Three - 100 KW. - 230
volts, D.C. units are installed.

CONFIDENTIAL

Classification (Confidential) (Controlled by Security Information)
By Engineering Department Date 12 May 1946 Handled 16 April 1949
By Engineering Department Date 12 May 1946 Handled MAY 16 1952

MUDSHIP SECTION

TEST A

JSS LST 546

Page 3 of 38 Pages

LST 546

CONFIDENTIAL

Classification (Confidential) (Controlled by Security Information)
By Engineering Department Date 12 May 1946 Handled 16 April 1949
By Engineering Department Date 12 May 1946 Handled MAY 16 1952

LST 546

PAGE 4 OF 38

TECHNICAL INSPECTION REPORT

OVERALL SUMMARY

I. Target Condition After Test.

(a) Drafts after test; list; general areas of flooding, sources.

There was no flooding, hence no change in drafts
or list.

(b) Structural damage.

HULL

None.

MACHINERY

No comment.

ELECTRICAL

There was no structural damage in way of
electrical equipment.

(c) Other damage.

HULL

Not observed.

MACHINERY

None.

ELECTRICAL

No damage occurred to electrical equipment due
to test A.

~~SECRET~~

USS LST 545

Page 5 of 33 Pages

II. Forces Evidenced and Effects Noted.

There was no evidence of heat in way of electrical equipment.

- | | | | | |
|--|-------|--------------|------------|---|
| (b) Fires and explosions. | HULL | MACHINERY | ELECTRICAL | There were no fires or explosions in way of electrical equipment. |
| | None. | No evidence. | | |
| (e) Effects peculiar to the atomic bomb. | HULL | | | |
| | | None. | | |
| | | | MACHINERY | None. |

There were no fires or explosions in way of electrical equipment.

- | | | | | | |
|-------------|------|-------|-----------|--------------|---|
| (c) Shock. | HULL | None. | MACHINERY | No evidence. | USS LST 545 |
| | | | | | Date 6 of 33 Pages
SECRET |
| ELECTRICAL. | | | | | Page 7 of 33 Pages
SECRET |
| | | | | | USS LST 545 |

Date 6/23 Page

8

Đại

57

6

8

8

Parte

四

1

1

MACHINERY

None. The vessel shifted berths under her own power after test A. At this time all machinery was tested except for a few units that were inoperable before test A. Performance was normal.

ELECTRICAL

No damage was apparent to electrical machinery or ship control.

(b) Effect on gunnery and fire control.

HULL

None.

MACHINERY

No comment.

ELECTRICAL

No damage was apparent.

(c) Effect on watertight integrity and stability.

HULL

None.

MACHINERY

No comment.

ELECTRICAL

No electrical damage affected watertight integrity or stability.

SECRET

USS LST 545

Page 8 of 33 Pages

(d) Effect on personnel and habitability.

HULL

None.

MACHINERY

None.

ELECTRICAL

No electrical damage affected personnel or habitability.

(e) Effect on fighting efficiency.

HULL

None.

MACHINERY

None.

ELECTRICAL

No electrical damage affected the fighting efficiency of the vessel.

IV. Summary of Observers' Impressions and Conclusions.

HULL

No comment.

MACHINERY

LST 545 was outside the effective range of the explosion in test A.

SECRET

USS LST 545

Page 9 of 33 Pages

USS LST 545

ELECTRICAL

No damage occurred to any electrical equipment
on this vessel due to the test.

V. Preliminary Recommendations.

HULL

None.

MACHINERY

None.

ELECTRICAL

None.

TECHNICAL INSPECTION REPORT

SECTION I - HULL

GENERAL SUMMARY OF HULL DAMAGE

I. Target Condition After Test.

- (a) Drafts after test; list; general areas of flooding, sources.
or list.

There was no flooding, hence no change in drafts

(b) Structural damage.

None.

(c) Other damage.

Not observed.

II. Forces Evidenced and Effects Noted.

(a) Heat.

None.

(b) Fires and explosions.

None.

(c) Shock.

None.

(d) Pressure.

The only evidence of pressure is that dirt inside
ventilation ducts was loosened and collected in the cheese cloth
screens at the duct terminals.

SECRET

USS LST 545

Page 10 of 33 Pages

USS LST 545

Page 11 of 33 Pages

(e) Effects peculiar to the atomic bomb.

None.

III. Results of Test on Target.

(a) Effect on machinery, electrical and ship control.
Not observed.

(b) Effect on gunnery and fire control.

None.

(c) Effect on watertight integrity and stability.

None.

(d) Effect on personnel and habitability.

None.

(e) Effect on fighting efficiency.

None.

IV. Summary of Observers' Impressions and Conclusions.

No comment.

V. Preliminary Recommendations.

None.

VI. Instructions for loading the vessel specified the following:

ITEM	LOADING	SECRET
Fuel oil	50%	
Diesel oil	50%	
Ammunition	50%	

SECRET

USS LST 545

Page 12 of 33 Pages

Potable and reserve feed water
Salt water ballast
No restriction
905

Details of the actual quantities of the various items aboard are included in Report 7, Stability Inspection Report, submitted by the ship's force in accordance with "Instructions to Target Vessels for Tests and Observations by Ship's Forces" issued by the Director of Ships Material. This report is available for inspection in the Bureau of Ships Crossroads Files.

USS LST 545

Page 13 of 33 Pages

DETAILED DESCRIPTION OF HULL DAMAGE

- A. General Description of Hull Damage.
No damage.
- B. Superstructure.
No damage. Dirt inside ventilation ducts was loosened and collected in the cheese cloth screens at the duct terminals.
- C. Turrets, Guns, and Directors.
No damage.
- D. Torpedo Mounts, Depth Charge Gear.
Not applicable.
- E. Weather Deck.
No damage. The main deck cargo and vehicle hatch covers were secured by straingbacks and did not move. Elastic deflection of the main deck, as recorded by scratch gages was approximately one inch. There was no permanent set.
- F. Exterior Hull.
No damage.
- G. Interior Compartments (above w.l.).
No damage.
- H. Armor Decks and Miscellaneous Armor.
Not applicable.
- I. Interior Compartments (below w.l.).
No damage.
- K. Tanks.
No damage.
- L. Flooding.
None.
- M. Ventilation.
No damage.
- N. Ship Control.
No damage.
- O. Fire Control.
No damage.
- P. Ammunition Behavior.
No damage.
- Q. Ammunition Handling.
No damage.
- R. Strength.
No damage.
- S. Miscellaneous.
No comment.

SECRET

USS LST 545

Page 15 of 33 Pages

USS LST 545

Page 14 of 33 Pages

SECRET

- J. Underwater Hull.
No damage.

USS LST 545

Page 16 of 33 Pages

TECHNICAL INSPECTION REPORT

SECTION II - MACHINERY

GENERAL SUMMARY OF MACHINERY DAMAGE

I. Target Condition After Test.

(a) Drafts after test; list; general areas of flooding, sources.

No data taken by machinery group.

(b) Structural damage.

No comment.

(c) Other damage.

None.

II. Forces Evidenced and Effects Noted.

(a) Heat.

No evidence.

(b) Fires and explosions.

No evidence.

(c) Shock.

No evidence.

(d) Pressure.

No evidence.

SECRET

USS LST545

Page 16 of 33 Pages

(e) Effects apparently peculiar to the atom bomb.

None.

III. Effects of Damage.

(a) Effect on machinery and ship control.

None. The vessel shifted berths under her own power after Test A. At this time all machinery was tested except for a few units that were inoperable before Test A. Performance was normal.

(b) Effect on gunnery and fire control.

No comment.

(c) Effect on water-tight integrity and stability.

No comment.

(d) Effect on personnel and habitability.

None.

(e) Total effect on fighting efficiency.

None.

IV. General Summary.

LST545 was outside the effective range of the explosion in Test A.

V. Preliminary Recommendation.

None.

SECRET

USS LST545

Page 17 of 33 Pages

USS LST545

Page 18 of 33 Pages

DETAILED DESCRIPTION OF MACHINERY DAMAGE

A. General Description of Machinery Damage.

(a) Overall condition.

The overall condition of the machinery was not changed by Test A.

(b) Areas of major damage.

None.

(c) Primary cause of damage in each area of major damage.

Not Applicable.

(d) Effect of target test on overall operation of machinery plant.

The target test had no effect on the overall operation of the machinery plant. All machinery was operated after the test. Performance was normal.

B. Boilers.

Neither the heating boiler nor its appurtenances were damaged by Test A.

C. Blowers.

Included under B.

D. Fuel Oil Equipment.

Included under B.

E. Boiler Feedwater Equipment.

Included under B.

SECRET

F. Main Propulsion Machinery.

Undamaged. Both main engines were operated when the ship shifted berths under her own power. Performance was normal.

G. Reduction Gears.

Undamaged. Performance was normal during operation of the main engines.

H. Shafting and Bearings.

Undamaged. Shafting and bearings were checked with the ship underway. Performance was normal.

I. Lubrication System.

Undamaged. The lube oil system was checked with the ship underway. Performance was normal.

J. Condensers and Air Ejectors.

Not Applicable.

K. Pumps.

Undamaged. All pumps have been tested at normal capacity and pressure.

L. Auxiliary Generators (Turbines and Gears).

Not Applicable.

M. Propellers.

Undamaged. Visual inspection from the surface reveals no indication of damage. Performance was normal with the ship underway.

N. Distilling Plant.

Undamaged. One unit was inoperable before Test A. Its condition was not changed by the test. The other unit was placed in operation immediately after the test, and functioned normally.

O. Refrigeration Plant.

Undamaged. The refrigerating plant was placed in service immediately after Test A, and functioned normally.

P. Winches, Windlasses, and Capstans.

Undamaged. All deck machinery was used in normal operation and tested under load after Test A.

Q. Steering Engine.

Undamaged. Performance was normal with the ship underway.

R. Elevators, Ammunition Hoists, Etc..

Undamaged. The tank deck elevator was operated after Test A, and functioned normally.

S. Ventilation (Machinery).

Undamaged. All vent motors and fans are operable and have been tested at full rating.

T. Compressed Air Plant.

Undamaged. The compressors have been tested at full load.

SECRET

USS LST545

SECRET

USS LST545

Page 19 of 33 Pages

USS LST545

Page 20 of 33 Pages

U. Diesels (Generators etc. Block.)

Undamaged. Generator #2 and #3 have been operated at full load with no indication of any damage. Generator #1 was inoperable before Test A. Its condition was not changed by the test.

V. Piping System.

Undamaged. The piping systems have been tested under pressure.

W. Miscellaneous.

Undamaged. Laundry, Galley, and machine shop equipment have been in operation since Test A. Performance was normal.

TECHNICAL INSPECTION REPORT

SECTION III - ELECTRICAL

GENERAL SUMMARY OF ELECTRICAL DAMAGE

I. Target Condition After Test.

- (a) Drafts after test; list; general areas of flooding, sources.

Drafts and list were the same as before Test A.
There was no flooding.

- (b) Structural damage.

There was no structural damage in way of electrical equipment. There was no damage to electrical equipment due to Test A.

- (c) Other damage.

No damage occurred to electrical equipment

II. Forces Evidenced and Effects Noted.

- (a) Heat.

There was no evidence of heat in way of electrical equipment.

- (b) Fires and explosions.

There were no fires or explosions in way of electrical equipment.

- (c) Shock.

There was no evidence of shock in way of electrical equipment.

SECRET

USS LST546

Page 21 of 33 Pages

USS LST545

Page 22 of 33 Pages

- (d) Pressure.
There was no evidence of pressure in way of electrical equipment.
- (e) Any effects apparently peculiar to the atom bomb.
Electrical equipment showed no evidence of damage peculiar to the atom bomb.

III. Effects of Damage.

- (a) Effect on propulsion and ship control.
No damage was apparent to electrical machinery or ship control.
- (b) Effect on gunnery and fire control.
No damage was apparent.
- (c) Effect on water-tight integrity and stability.
No electrical damage affected water-tight integrity or stability.
- (d) Effect on personnel and habitability.
No electrical damage affected personnel or habitability.
- (e) Total effect on fighting efficiency.
No electrical damage affected the fighting efficiency of the vessel.

- IV. General Summary of Observers' Impressions and Conclusions.
No damage occurred to any electrical equipment on this vessel due to the test.
- V. Any Preliminary General or Specific Recommendations of the Inspecting Group.
None.

SECRET

USS LST545

SECRET

USS LST545

DETAILED DESCRIPTION OF ELECTRICAL DAMAGE

A. General Description of Electrical Damage.

(a) Overall condition.

The overall condition of the electric plant is the same as before the test.

(b) Areas of major damage.

None.

(c) Primary causes of damage in each area of major damage.

None.

(d) Effect of target test on overall operation of electric plant.

1. Ship's service generator plant - no effect.
2. Engine and boiler auxiliaries - no effect.
3. Electric propulsion - not applicable.
4. Communications - no effect.
5. Fire control circuits - no effect.
6. Ventilation - no effect.
7. Lighting - no effect.

(e) Types of equipment most affected.

None.

B. Electric Propulsion Rotating Equipment.

Not Applicable.

C. Electric Propulsion Control Equipment.

Not Applicable.

D. Generators - Ships Service.

No damage.

E. Generators - Emergency.

Not Applicable.

F. Switchboards, Distribution and Transfer Panels.

No damage.

G. Wiring, Wiring Equipment and Wireways.

No damage.

H. Transformers.

No damage.

I. Submarine Propelling Batteries.

Not Applicable.

J. Portable Batteries.

No damage.

K. Motors, Motor Generator Sets and Motor Controllers.

No damage.

SECRET

USS LST545

SECRET

USS LST545

Page 25 of 33 Pages

SECRET

Page 26 of 33 Pages

USS LST545

- | | | | |
|----|----------------------------|----|-------------------------------|
| L. | Lighting Equipment. | U. | I.C. and A.C.O. Switchboards. |
| | No damage. | | Not Applicable. |
| M. | Searchlights. | V. | F.C. Switchboards. |
| | No damage. | | Not Applicable. |
| N. | Degaussing Equipment. | | |
| | No damage. | | |
| O. | Gyro Compass Equipment. | | |
| | No damage. | | |
| P. | Sound Powered Telephones. | | |
| | No damage. | | |
| Q. | Ship's Service Telephones. | | |
| | No damage. | | |
| R. | Announcing Systems. | | |
| | No Applicable. | | |
| S. | Telegraphs. | | |
| | No damage. | | |
| T. | Indicating Systems. | | |
| | No damage. | | |

SECRET


USS LST545

SECRET

USS LST545

Page 27 of 33 Pages

Page 28 of 33 Pages



SECTION IV

PHOTOGRAPHS

TEST ABLE

SECRET
USS LST 545

Page 29 of 33 Pages

AA-CR-227-87-75. View from off starboard beam after Test A.

SECRET
USS LST 545
192

Page 30 of 33 Pages

AA-CR-227-87-78. View from off port bow after Test A.

SECRET
Page 31 of 33 Pages
USS LST 545
0926

SECRET
Page 32 of 33 Pages
USS LST 545
0926

USS LST 545

Page 32 of 33 Pages

SECRET

TESTABLE

COMMANDING OFFICERS REPORT

APPENDIX

CONFIDENTIAL

REPORT # 11

COMMANDING OFFICERS REPORT

SECTION I

The U.S.S. LST #545 was anchored in Berth #18, 4000 yards north of the U.S.S. NEVADA. The material condition of the hull and superstructure at the time of the test was excellent; the material condition of the Engineering Department was poor. The overall condition was such that damage to test equipment, inflammables and ammunition could have been controlled.

There was no damage to the ship as a result of the test and the ability of the ship to operate or fight was not impaired.

The target test had no damaging effect whatsoever on the ship. There is no evidence of fires, extreme heat, or damage to any part of the ship. Extreme pressures were present and their effect was noted on the deck compression gauges. The scratch pattern on the gauges shows that the hull of the ship compressed and expanded very rapidly with an accordian like movement but after the passing of the blast, the hull returned to its original pattern. From all indications, it is considered that it would have been possible for the ship to have remained in operation both during and after the test. It is also believed that it would have been conceivable possible for personnel to have remained at their stations below decks and not have suffered major injuries from the blast.

SECRET

U.S.S. LST 545

Page 33 of 33 Pages

CONFIDENTIAL

CAUTION

This Document Contains
ATOMIC WEAPONS INFORMATION

NOTICE

This document contains atomic weapons information. Distribution is limited to recipients authorized by the Defense Atomic Support Agency (DOD) and/or the Division of Military Application (AEC)



Defense Special Weapons Agency
6801 Telegraph Road
Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER
ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

/ ✓ AD-366588 L	XRD-203-Section 12 ✓
AD-366589 L	XRD-200-Section 9
AD-366590 L	XRD-204-Section 13
AD-366591 L	XRD-183
/ ✓ AD-366586 X	XRD-201-Section 10 ✓
/ ✓ AD-367487 X	XRD-131-Volume 2-
/ ✓ AD-367516 X	XRD-143 ✓
/ ✓ AD-367493 X	XRD-142 ✓
AD-801410L ✓	XRD-138 ✓
AD-376831L ✓	XRD-83 ✓
AD-366759 L	XRD-80
/ ✓ AD-376830L X	XRD-79 ✓
/ ✓ AD-376828L X	XRD-76 ✓
/ ✓ AD-367464 X	XRD-106 ✓
AD-801404L ✓	XRD-105-Volume 1 L
/ ✓ AD-367459 X	XRD-100 ✓

TRC

18 April 1997

Subject: Declassification of Report

AD-376836L✓	XRD-98✓
AD-376835L✓	XRD-97✓
AD-376834L✓	XRD-96✓
AD-376833L✓	XRD-95✓
✗ AD-376832L✓	XRD-94✓ <i>re-ingest</i>
✓✓ AD-367458✗	XRD-93✓
AD-367457✓	XRD-92-Volume 2
AD-367456✓	XRD-91-Volume 1
AD-367455✓	XRD-90
AD-367454✓	XRD-89
AD-367453✓	XRD-88
AD-367452✓	XRD-87
AD-366764✓	XRD-86
AD-376837L✓	XRD-99
AD-366758✓	XRD-78
AD-366734✓	XRD-44
AD-366763✓	XRD-85
AD-376829L✓	XRD-77✓
✓✓ AD-367462✗	XRD-103✓
✓✓ AD-367463✗	XRD-104✓
✓✓ AD-367461✗	XRD-102✓
AD-367460✓	XRD-101

TRC

18 April 1997

Subject: Declassification of Reports

AD-801406L ✓ XRD-114?

In addition, all of the cited reports are now **approved for public release; distribution statement "A" now applies.**

Ardith Jarrett
ARDITH JARRETT
Chief, Technical Resource Center